## **Information Sheet 1**

## JOINTER SAFETY RULES

A jointer carelessly handled is a dangerous machine. You must respect its high operating speeds, its sharp knives, and its ability to kick back. When you operate a jointer you should observe the following:

- 1. Follow all General Shop Safety Rules.
- 2. Check the condition of stock before jointing. Make sure it is free from nails, paint or other foreign material.
- 3. Do not take heavy cuts. 1/32" to 1/16" is normal.
- 4. Never pass your hands directly over the cutter-head.
- 5. Do not drag your thumb at the back end of the stock, keep your fingers as high as possible on the side of the stock
- 6. Use push blocks and/or push sticks whenever possible. Fingers should be kept a minimum of 3" away from the cutter at all times.
- 7. Do not edge-joint stock that is less than <sup>3</sup>/<sub>4</sub>" high, use a push block or stick for narrow stock
- 8. Do not face stock that is less than  $\frac{1}{2}$ " thick, use a push block for all thin material
- 9. Keep the work area free of debris; use a cart to store stock waiting for jointing do not lay it on the infeed/outfeed table, or on the floor where it can pick up debris.
- 10. Allow the cutterhead to reach full speed before you start a cut and do not leave the jointer until the cutterhead comes to a full stop.
- 11. Keep the guard in place, unless a specific operation requires its removal.
- 12. Always use the fence to guide the stock when edge jointing. Make sure it is locked in position before starting.
- 13. Do not joint pieces less than 12" long.
- 14. Joint "with the grain" whenever possible.
- 15. Reset the depth of cut to 1/32" when you have finished using the jointer.