
Information Sheet 2

GRAIN DIRECTION DIAGRAM

When joining the EDGE of the stock, check the grain direction of the SIDE of the work piece.



NOTE: When the cutter head is below the stock, as on the jointer, the knives will *exit* the stock <u>toward your feet</u>. The wood grain should be oriented in the same general direction